


# Cable Tray SWING (1200 mm)




## Assembly Manual


Read this manual thoroughly and store in a safe place!

## Content box


| #  | Part name                      | Qty |
|----|--------------------------------|-----|
| 01 | Pre Assembly Cable Tray 1200mm | 1   |
| 02 | Tray Guide Cap - Right         | 1   |
| 03 | Tray Guide Cap - Left          | 1   |
| 04 | Screw PH Chipboard 4.5 x 16mm  | 6   |



01



02




03



04



1




### Adjusting the frame wide

- Pull the frame outward to the minimum 1300mm wide.




2



- Put the pre-assembly cable tray 1200mm at the centre of the table top.
- Slot the tray guide cap right and tray guide cap left into the spring pin.





3



- Leave 5mm gap between the pre-assembly cable tray and the tray guide cap right and left.




4



- Tighten the 6x chipboard screw with screw driver.

## Mounting Direction

Option 1



Option 2

